

Avoid this common & costly goof

Need Help Now?

Call 800-320-4044 or [email us](mailto:sales@houstonvibrator.com)
for immediate assistance.

Over-Vibration is THE #1 GOOF in Industrial Vibrator Selection – and it can really cost you.

A material flow problem can be a very costly issue, leading to inconsistent batches, lost production, and downtime for your facility. The tendency when facing a flow problem is to want it solved fast and solved for good. In the hurry to fix the problem, many users tend to select a vibrator too large for their equipment. This causes a whole new set of problems that can be even more costly than the original flow problem! And you may not see the effects right away.

One of the key rules in industrial vibrator sizing is “Never over-vibrate” – and with good reason. When too much force is applied to a structure, of course the flow problem is alleviated in the short term. However, extra cost is associated in purchasing a larger model than needed, running and maintaining it, AND, worst of all, the structure it’s mounted on is now exposed to forces that can lead to damage or complete destruction over time. When you consider the cost of repairing or replacing your equipment, not to mention the cost of the downtime associated with that, it just doesn’t make good sense to take the “Shake the daylight out of it” approach.

Do you KNOW how to properly size vibrators for your equipment?

When faced with a material flow problem, we encourage you to take a small amount of extra time up front to consult an expert on choosing the right vibrator for the job, saving yourself time and money now and in the future. At Houston Vibrator, our sales force is trained to review the details of your problem, the needs of your facility, and the specifics of the structure you need vibrated. When properly sized and installed, industrial vibrators can alleviate any number of flow problems, improving the efficiency of your processes, and ensuring the longevity of your equipment.

For immediate assistance with a flow problem in your facility, or to have an expert review the vibrators you’ve already got installed, contact Houston Vibrator at 800-320-4044 or email us at sales@houstonvibrator.com.

For additional money-saving maintenance tips that can help to extend the life of your vibrators and the equipment they’re mounted on, review our General Vibrator Maintenance Tips.

Houston Vibrator, Ltd.
PO Box 801882
Houston, TX 77280
U.S.A.

phone: 713-939-0404 | 800-320-4044
fax: 713-939-7213 | 866-630-0404
e-mail: sales@houstonvibrator.com
web: www.HoustonVibrator.com

